

## FHA Non-Compliant Photos

This is an illustration of an enclosure wall that is not compliant. (Vinyl Skirting)FHA/HUD approved anchoring system This is of a non-compliant pier. It is a dry stacked pier and is not mortared and is not supported with a poured footer. This photo is a non-compliant ground anchor. (Not anchored in concrete) Non-compliant pier. Pier is not setting on a poured footer.